

How to upgrade TP-LINK Range Extender

Part A: Please read this section carefully before upgrade

1. Please verify the hardware version of your device match with the firmware you downloaded. Any incorrect firmware upgrading may damage your device and void the warranty.



RE200(US)_V3_181219		
Published Date: 2019-01-17	Language: Multi-language	File Size: 7.81 MB

Modifications and Bug Fixes:

1. Enhanced the display on Safari browser.
2. Fixed the problem on connection with Archer VR900.
3. Fixed some bugs on AP mode.

Notes:

1. For RE200_V3.0.

2. After you downloaded the firmware from TP-LIK website, please use decompression software such as WinZIP or WinRAR to extract the firmware file to a folder;

3. **Do NOT turn off the power during the upgrade process, as it may cause permanent damage to the product.**

4. To avoid wireless disconnect issue during firmware upgrade process, it's recommended to upload firmware with **wired connection** unless there is no LAN/Ethernet port on your TP-LINK device.

5. It's recommended that users stop all Internet applications on the computer, or simply disconnect Internet line from the device before the upgrade.

Part B: Please follow the steps below to upgrade firmware version

Step 1 Log into the TP-LINK device by typing <http://tplinkrepeater.net/> in the address bar of the web browser (such as Google Chrome). Type the **Password** of the web management page.



Step 2 Click **Settings > System Tools > Firmware Upgrade**, click the **Browse** button to choose the firmware you already extracted in the folder.

Hardware Version: TL-WA850RE(EU)7.0

Firmware Version: 1.0.0 Build 190805 Rel.64784n (6985)

New Firmware File:

BROWSE

UPGRADE

Step 3 Click the **Upgrade** button. The device will reboot automatically after the upgrading has been finished. Please wait about 3~5 minutes.

Step 4 Go back to the same page as **Step2**, verify that the device's firmware has been upgraded.