

Recommended Controller Software Version: Omada Controller v4.1.5 or above

New Feature/Enhancement:

1. The LED light will blink once and then stay on bright when the power is applied.

Bug fixed:

1. Fixed the bug that clients cannot connect to the SSID with wpa-psk encryption.
2. Fixed the bug that after roaming back and forth between Root AP and Mesh AP, clients fail to ping the Mesh AP.

Notes:

1. For EAP620HD v2 only.
2. This version of firmware is applied to the Omada APP of version 3.0.X or above.
3. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP620HD, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.