

Recommended Controller Software Version: Omada Controller v4.1.5 or above

Bug fixed:

1. Fixed the bug that clients cannot get IP address if SSID VLAN enabled when EAP connects to a switch with port priority.
2. Optimized for security vulnerabilities.
3. Fixed the bug that sometimes showing wrong client number in Controller mode.

Notes:

1. For EAP615-Wall v1 only.
2. Follow IC certification in Canada, can't downgrade to US/EU version any more if upgrade this firmware.
3. This version of firmware is applied to the Omada APP of version 3.0.X or above.
4. **This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP615-Wall, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.**