
RELEASE NOTE

For the following model:

Product Description: AC1200 Wireless Dual Band Gigabit VoIP VDSL/ADSL Modem Router

Model No: Archer VR1210v 1.0

Trademark: **TP-Link**

File Name: Archer VR1210v v1_2.0.0 0.9 v6041.0 Build 220304 Rel.6349n.bin

Release Time: 2022.3.9

MD5: c846bd07b9aaf6047b5058520ecab7df

Firmware Version: 2.0.0 0.9 v6041.0 Build 220304 Rel.6349n

Modifications:

1. Support English(default), Italian, and Spanish Language
2. Default Region UK, Default Timezone GMT+ 00:00
3. VoIP password with * sign after saving the settings.
4. Support DHCP Option 43 on WAN interface for autoprovisioning
5. "Agile Config 2.0(global & mac.bin, logo, favicon, url)
For LAN port, Agile Config Tool 2.0 is requested. Device will not reboot automatically after Agile Config(WISP can directly cut off the power supply), and the new configuration will be activated only after end users power on the device."
6. Support TLS v1.2
7. Fix the problem that two Bye packets will be sent after the phone hangs up
8. Fix the problem of PPPoE DHCPv6