

Recommended Controller Software Version: Omada Controller v4.1.5 or above

Bug Fixed:

1. Optimize the abnormal switching on/off problem.

Notes:

1. For EAP650 v1/v1.20/v1.26 only.
2. This version of firmware is applied to the Omada APP of version 3.0.X or above.
3. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP650, you must upgrade the Omada controller to version 4.1.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade omada controller.