

This firmware is fully adapted to Omada SDN Controller 5.8.

Bug Fixed:

1. Fix the bug that DHCP Server cannot assign an IP address when a large number of clients make DHCP requests at the same time.
2. Fixed the bug of not being able to assign the correct reserved IP address.
3. Fix the bug that slow loading when accessing Web UI with Chrome kernel browser.

Notes:

1. For ER605 v2.0 and v2.6 only.
2. Your device's configuration won't be lost after upgrading.