

Recommended Controller Software Version: Omada Controller v5.5 or above

Bug fixed:

1. Fix the EAP's web management page becomes unreachable under some circumstances.
2. Fix the EAP's CPU utilization is abnormally high under some circumstances.
3. Fix some clients could be in multiple VLANs at the same time.
4. Fix the EAP won't apply multicast-unicast conversion for 5G SSIDs.
5. Fix in WPA-Enterprise authentication, the *NAS_IP_Address* parameter is used as 192.168.0.254 but not the EAP's actual IP address.
6. Fix the accounting interim update period is incorrect when the value is set above 128s.

Notes:

1. For EAP615-Wall v1 only.
2. This version of firmware is applied to the Omada APP v3.0.X or above.
3. **This firmware is fully adapted to Omada SDN Controller v5.5 or above. If you are using the old Omada Controller and need to manage EAP615-Wall, you must upgrade the Omada Controller to v5.5 or above. You can follow [Omada Controller Upgrade Guide](#) to upgrade Omada Controller.**