

## TP-Link FW Release Notes

<b>Product Name</b>	EX220(EU)1.0	
<b>Firmware Version</b>	0.18.0 2.0.0 v605f.0 Build 230906 Rel.42714n	
<b>Release Date</b>	Nov 17, 2023	
<b>Release purposes:</b> <b>New Features</b> <b>Feature Changes</b> <b>Enhancements</b> <b>Fix some bugs.</b>		
<b>Change items (Include New features, feature changes, bug fix)</b>		
<b>No.</b>	<b>Description</b>	<b>Note</b>
1	Support Aginet Config 3.0.	New Features
2	Support IPv6 MAP-E	New Features
3	Support TWT & OFDMA	New Features
4	Support IPv6 in Multi SSID	New Features
5	Support TAUC1.1	New Features
6	Support IPV6 passthrough	New Features
7	Support Mac VLAN	New Features
8	Support Hardware QoS	New Features
9	Change CWMP Setting, telnet&SSH Setting to appear only in the superadmin mode by default	Feature Changes
10	Optimized bootloader Recovery Mode	Enhancements
11	Optimized TR-181 Parameter	Enhancements
12	Optimized Mesh Roaming Compatibility	Enhancements
13	Optimized loopback suppression mechanism in AP mode	Enhancements
14	Optimized controller switching function in A+A Easymesh networking	Enhancements
15	Optimized TR-143 Upload Performance	Enhancements
16	Optimized TAUC Stability	Enhancements
17	Optimized Download Performance in PPTP/L2TP connection	Enhancements
18	Optimized Easymesh Routing	Enhancements
19	Fixed Some Internet Stability Issues	Bugfix
20	Fixed Some Aginet Config Issues while using Multi	Bugfix

---

	<b>WAN Connection and Changing Status of Bandsteering Function</b>	
<b>21</b>	<b>Fixed ICMP Ping Issue while enabled Guest WiFi after router connecting to the Internet</b>	<b>Bugfix</b>
<b>22</b>	<b>Fixed login issue after all the Easymesh devices reset</b>	<b>Bugfix</b>
<b>23</b>	<b>Fixed the issue that TAUC continuously import WAN Configuration</b>	<b>Bugfix</b>
<b>24</b>	<b>Fix several Easymesh Boot bugs</b>	<b>Bugfix</b>
<b>25</b>	<b>Fix the issue that Aginet APP cannot Reboot or Remove Agent Device</b>	<b>Bugfix</b>
<b>26</b>	<b>Fixed some Easymesh Stability Issues</b>	<b>Bugfix</b>