Built-in Omada SDN Controller 5.13.30.20

1. Supported Device Models and Firmware

EAP

EAP783, EAP773

EAP690E HD, EAP683 LR, EAP680, EAP673, EAP670, EAP660 HD

EAP655-Wall, EAP653, EAP650-Outdoor, EAP650-Wall, EAP650, EAP620 HD

EAP615-Wall, EAP615-Wall, EAP613, EAP610-Outdoor, EAP610

EAP265 HD, EAP235-Wall, EAP230-Wall, EAP225-Outdoor, EAP223

EAP215-Bridge KIT, EAP211-Bridge KIT

EAP115-Bridge KIT, EAP115-Wall, EAP113-Outdoor

EAP245 V3, EAP225 V3, EAP225-Wall V2, and above versions

EAP115 V4, EAP110 V4, EAP110-Outdoor V3, and above versions

Switch (TL- prefix ignored for some models)

SX6632YF SG6428X, SG6428XHP, SG6654X, SG6654XHP

SG3218XP-M2, SG3210X-M2, SG3210XHP-M2

SX3016F, SX3008F, SX3206HPP

SG3452XP, SG3452X, SG3452P, SG3452

SG3428X-M2, SG3428XPP-M2

SG3428XMP, SG3428XF, SG3428X, SG3428X-UPS

SG3428MP, SG3428, SG3210XHP-M2

SG2428P, SG2218P, SG2218, SG2016P, SG2210MP, SG2008P

SG3210 V3, SG2210P V3.2, SG2008 V3, SL2428P V4, and above versions

Router

ER7206 V1 (TL-ER7206 V1) and V2, ER707-M2, ER706W-4G, ER706W

ER605W, ER605 V1 (TL-R605 V1) and V2

New Features & Enhancements

- 1. Added support for Layer-3 Switch features:
 - QoS
 - VRRP
 - OSPF
 - STACK
 - STP Extension
- 2. Optimized the PUBLIC IP ADDRESS column in Devices List.
- 3. Optimized the Global View for viewer account, allowing users with Viewer permissions to see the Sites they can access in the Global View.
- 4. Optimized the name of "AI WLAN Optimization" to "WLAN Optimization", removed the Schedule module.
- 5. Optimized the Controller version number to 4 digits, the Backup files are compatible when the first three digits are identical, improving Site import and migration.
- 6. Optimized the PMF mode automatic selection logic and the prompts when PMF/WPA mode changes.
- 7. Optimized the clarity of some texts and icons in Dark mode.
- 8. Optimized the logic of the authentication logs update.

Bug Fixed

- 1. Fixed the bug that the Static IP of WAN port could not be set with a 31-bit mask.
- 2. Fixed the bug that some models' firmware can't be upgraded online, but only through manual upgrade.
- 3. Fixed the bug that the clients can't connect the SSID with MAC Filtering under some certain configuration steps.
- 4. Fixed the bug that Controller takes up a lot of disk space after running for a long time.
- 5. Fixed the bug that LTE models lose the Internet after changing the Rate Limit via Open API.
- 6. Fixed the bug that the Tx Power (EIRP) setting of the EAP changes to High after the reboot, although the actual EIRP maintains.
- 7. Fixed the bug that Batch Config of WLAN Group doesn't work for EAPs.
- 8. Fixed the bug of the display error of some models in Device Map.
- 9. Fixed the bug of failing to create SSID via Open API.

Notes

- 1. This version of the Controller is fully applied to the Omada APP of version 4.14 or above.
- 2. Omada SDN Controller can only manage certain devices running the supported firmware. Please confirm that your device is compatible with the SDN Controller.
- 3. Once upgraded to this version of Omada Controller, you will be **NOT** able to downgrade to version 3.2.17 or below.