

## Release notes for ER8411(UN) 1.0

### 1.Version Info:

Adapted Model: ER8411(UN) 1.0

Fully Adapted Controller Version: SDNC 5.15

Minimum FW Version for Update: 1.2.3 Build 20241121 Rel.21021 and above, for downloading of any firmware version, please refer to [Omada Download Center](#).

### 2.Bug Fixes:

- 1) Fixed the issue that ports cannot switch back to 10G after being changed to 1G in Controller mode.
- 2) Fixed the issue of address pool exhaustion logs and device disconnection after upgrading to version 1.3.1.