

## **Version Info:**

**Firmware for SX3832(UN) 1.0/1.6. This firmware is fully adapted to Omada Controller V5.15.24**

### Enhancements

1. Optimize the performance of mass VLAN management.
2. Optimize MAB authentication interception function.

### Bug fixed

1. Fixed the problem of continuous reporting of DDM abnormal alarm information in some scenarios.
2. Fixed spanning tree exceptions in special scenarios.
3. Fixed the problem of exceptional scene recognition of the client recognition function.