

Version Info:

Firmware for S6500-48G6XF(UN) 1.0. This firmware is fully adapted to Omada Pro Controller V1.10.20

SHA256:620174131f3638bb71a05d59a11270111d6438001b003ca8cfdb17bdb1444fd3

SHA512:48e5dfd5450525104fc0275676d8c5c5eaa2be9c3531fd7ae603fc446e42540d12d1ae5259b6d396cdd2a40f2c8b923aa13a58fba1029fd10de766e3b0eed60b

Enhancements

1. Optimized internal communication mechanism for stacking to improve stability.
2. Enhanced M-LAG stability.
3. Improved MAC address migration stability in M-LAG scenarios.

Bug fixed

1. Fixed the issue where IP addresses could not be obtained from the DHCP server in M-LAG scenarios.
2. Fixed the issue where Layer 3 traffic could not quickly recover after interruption in M-LAG scenarios.
3. Fixed the abnormal synchronization of full-capacity FDB entries in M-LAG scenarios.