Release Note for ER605(UN) v2.0/v2.6/v2.8/v2.20/v2.26 and ER605(IN) v2.28

Important Notice:

This firmware resolves several security vulnerabilities.

Version Info:

- 1. Applied Models:
 - a) ER605(UN) v2.0
 - b) ER605(UN) v2.6
 - c) ER605(IN) v2.8
 - d) ER605(UN) v2.20
 - e) ER605(UN) v2.26
 - f) ER605(IN) v2.28
- 2. Firmware Version: 2.3.1 Build 20251015 Rel. 78291
- 3. Minimum FW Version for Update:
 - a) UN v2.0: 2.2.3 Build 20231201 Rel.32918 and above
 - b) UN v2.6: 2.2.3 Build 20231201 Rel.32918 and above
 - c) UN v2.8: 2.2.3 Build 20231201 Rel.32918 and above
 - d) UN v2.20: 2.2.3 Build 20231201 Rel.32918 and above
 - e) UN v2.26: 2.2.3 Build 20231201 Rel.32918 and above
 - f) IN v2.28: 2.2.3 Build 20231201 Rel.32918 and above

For downloading of any firmware version, please refer to <u>Omada Download</u> Center.

- 4. Recommended Controller Version: 5.15.20
- 5. Recommended APP Version: No

New Features:

No	
Enhancements:	
No	
Bug Fixed:	
1.	Resolved several security vulnerabilities.

Additional Information:

No.