

# Release Note for ER605(UN) v2.0/v2.6/v2.20/v2.26/v2.30/v2.36 and ER605(IN) v2.8/v2.28/v2.38 and ER605(BR) v2.36

## Important Notice:

This firmware upgrade is irreversible. Please contact Omada technical support if downgrade is required.

Only the firmware version number and signature algorithm are different from version 2.3.2 Build 20251029 Rel.12727.

## Version Info:

### 1. Applied Models:

- a) ER605(UN) v2.0
- b) ER605(UN) v2.6
- c) ER605(IN) v2.8
- d) ER605(UN) v2.20
- e) ER605(UN) v2.26
- f) ER605(IN) v2.28
- g) ER605(UN) v2.30
- h) ER605(UN) v2.36
- i) ER605(IN) v2.38
- j) ER605(BR) v2.36

### 2. Firmware Version: 2.3.3 Build 20251029 Rel.18054

### 3. Minimum FW Version for Update:

- a) UN v2.0: 2.3.2 Build 20251029 Rel.12727
- b) UN v2.6: 2.3.2 Build 20251029 Rel.12727
- c) IN v2.8: 2.3.2 Build 20251029 Rel.12727
- d) UN v2.20: 2.3.2 Build 20251029 Rel.12727
- e) UN v2.26: 2.3.2 Build 20251029 Rel.12727

- 
- f) IN v2.28: 2.3.2 Build 20251029 Rel.12727
  - g) UN v2.30: 2.3.2 Build 20251029 Rel.12727
  - h) UN v2.36: 2.3.2 Build 20251029 Rel.12727
  - i) IN v2.38: 2.3.2 Build 20251029 Rel.12727
  - j) BR v2.36: 2.3.2 Build 20251029 Rel.12727

For downloading of any firmware version, please refer to [Omada Download Center](#).

**4. Recommended Controller Version: 5.15.20**

**5. Recommended APP Version: No**

**New Features:**

No.

**Enhancements:**

No.

**Bug Fixed:**

No.

**Additional Information:**

1. Use a more secure signature algorithm to enhance device security.