

Version Info

Firmware for S6500-48M6Y(UN) 1.0. Recommended Omada Controller V6.0.0.

SHA-256

7c360ce55b4b51f161487dc49a6d1b6822cf95df1232479a20fd187867c3fbb8

SHA-512

**ca60ac9244e4dccde5e5a118b29c72b237c31660544a20e81e0e9d4f30579dae84f2a
ea63833f0e895df4c7d74cfae2f773f363597392cf40c6857450b1936ad**

New features

1. Changed the default FEC mode of cascade ports to enabled.

Enhancements

1. Enhanced the stability of the stacking feature.
2. Improved M-LAG stability.
3. Strengthened device password configuration security.

Bug fixed

1. Fixed an issue where the DHCP Server might exit abnormally when allocation was near full capacity.
2. Fixed a problem where the VLAN trunk function could cause VLAN hardware configuration errors.
3. Fixed an issue where the OSPFv3 process might exit abnormally during interface flapping.
4. Fixed an issue where the spanning tree status was incorrect in M-LAG topologies in certain scenarios.
5. Fixed an issue where the LAG status was incorrect in M-LAG topologies in certain scenarios.
6. Fixed an issue causing adoption disconnection with Omada Controller in certain scenarios.