

Version Info

Firmware for S7500-48XF4C(UN) 1.0. Recommended Omada Controller V6.0.0.

SHA-256

02056db599d37ffb57b75bc483c01b3daca5294763bd62fed5d9ad02d4adbdf2

SHA-512

ce8c22cc72e90865ca62964208849eb40b42a63aad76d7a7de1fdb63731a0912925d
3a80ca3a79b25ddf88bded54027e146862bc1868b13ea20b49f9da246257

New features

1. Changed the default FEC mode of cascade ports to enabled.

Enhancements

1. Enhanced the stability of the stacking feature.
2. Improved M-LAG stability.
3. Strengthened device password configuration security.

Bug fixed

1. Fixed an issue where the DHCP Server might exit abnormally when allocation was near full capacity.
2. Fixed a problem where the VLAN trunk function could cause VLAN hardware configuration errors.
3. Fixed an issue where the OSPFv3 process might exit abnormally during interface flapping.
4. Fixed an issue where the spanning tree status was incorrect in M-LAG topologies in certain scenarios.
5. Fixed an issue where the LAG status was incorrect in M-LAG topologies in certain scenarios.
6. Fixed an issue causing adoption disconnection with Omada Controller in certain scenarios.