

Version Info:

1. Minimum FW Version for Update: 1.2.0 Build 20240830 Rel. 50742.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 6.0 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Improved the stability of wireless client connections.
2. Optimized the CLI framework and updated certain text descriptions.

Bug fixed:

1. Fixed an issue where, in certain cases, after the AP detected radar signals on a DFS channel and switched to an alternate channel, it failed to return to the configured channel after 30 minutes.
2. Fixed an issue where, enabling both WPA3 Encryption and 802.11r would cause abnormalities in certain scenarios.
3. Fixed an issue where, changing the WPA3 encryption type in Standalone mode occasionally failed to take effect.
4. Fixed an issue related to the reporting of certain DHCPv6 information.

Notes:

1. This version of firmware is applied to the Omada APP 5.0 or above.