

Bug fixed:

1. Fixed a DHCP compatibility issue that could prevent the device from obtaining an IP address when connected to certain gateways.

Notes:

1. For TL-SG1016PE(UN) V6.0.
2. Your device's configuration will be retained after the upgrade, but it is still recommended to backup configuration before the upgrade.