

Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20251030 Rel. 58575.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 5.14 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Bug fixed:

1. Fixed an issue where clients connected to the SSID assigned to VLAN 1 could not access the Internet after changing the default VLAN.
2. Fixed an issue where client counts displayed in the SSID List were incorrect when the APP managed a configuration with eight 5+6 GHz MLO SSIDs and one 2.4 GHz SSID.
3. Fixed an issue where untagged wireless clients could successfully ping but could not establish TCP connections with clients within a VLAN.
4. Fixed an issue where MLO clients were not correctly included in RADIUS accounting in certain conditions under controller management.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.