

## Version Info:

Firmware for SX3832(UN) 1.20,SX3832(UN) 1.26. Recommended Omada Controller V6.0.0.

## New features

1. Added support for power extend.

## Bug fixed

1. Fixed the issue of IP loss caused by repeated modification of VLAN configuration by the controller.
2. Fixed HTTP JSON data memory leak issue.
3. OAM OUI modification.
4. LLDP-MED function Country Code modification.