

Version Info:

1. Minimum FW Version for Update: 1.1.2 Build 20251030 Rel. 58575.
2. This firmware upgrade is irreversible. Contact Omada technical support if downgrade is required.
3. Recommended Omada Controller version 5.14 or above.
4. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.

Bug fixed:

1. Fixed an issue where, under APP management, after creating eight 5+6 GHz MLO SSIDs and one 2.4 GHz SSID, the Wireless>SSIDs List failed to display the correct client count when clients connected to an MLO SSID; additionally, when clients connected to the 2.4 GHz SSID, the displayed client count in the SSID List was incorrect.
2. Fixed an issue where wireless clients without VLAN configuration could ping wireless clients within a VLAN, but may were unable to transmit TCP data between them.
3. Fixed an issue where, when the controller managed the device with Enterprise-Encryption and RADIUS accounting enabled, MLO clients connected through an MLO SSID were not correctly accounted for.
4. Fixed an issue where clients connected to the SSID configured with VLAN 1 could not access the Internet after modifying the default VLAN.

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.