

Version Info:

1. Minimum FW Version for Update: 1.0.0 Build 20251203 Rel. 57193.
2. Recommended Omada Controller version 5.15.24 or above.
3. For downloading of any firmware version, please refer to Omada Download Center.

Bug fixed:

1. Fixed an issue where roaming on an MLO SSID could cause clients to be unable to obtain an IP address for a period of time.
2. Fixed a stability issue where Xiaomi 14 Ultra devices experienced problems when associating to the 2.4 GHz band.
3. Fixed an issue where portal authentication might fail in certain scenarios.
4. Fixed an issue where, under PPSK with RADIUS unbound MAC configuration, mandatory PMF caused client association failure.
5. Fixed an issue where the 6 GHz SSID disappeared in specific scenarios.
6. Fixed an issue where 802.11r behavior did not meet expectations when used with specific wireless clients.

Note:

1. This version of firmware is applied to the Omada APP 5.0 or above