

Version Info:

1. Minimum FW Version for Update: 1.1.5 Build 20250928 Rel. 68499.
2. Recommended Omada Controller version 5.15 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#) .

Enhancements:

1. Optimized UI menu style for Standalone mode.

Bug fixed:

1. Fixed an issue where, when enabling manual DST in controller Site Settings, DST would start two hours earlier if the time zone was set to UTC+2.
2. Fixed an issue where, under standalone management with DST enabled, modifying the system time within the DST period caused the system time to add the offset again.
3. Fixed an issue where, under standalone management, the mPort in the Controller Inform URL was set to 0, while it should be 29814.
4. Fixed an issue where, when configuring a static IP in standalone mode, the gateway address field had no mandatory prompt and could be saved even if left empty.
5. Fixed an issue where, after zooming in the browser while accessing the AP standalone management interface, the VLAN field under Wireless → VLAN ID configuration displayed abnormally.
6. Fixed an issue where, when channel limit was disabled in standalone mode, the option "Allow DFS channel scanning" in channel optimization could not be turned off.
7. Fixed an issue where, after channel limit was enabled and radar waves were detected, the channel optimization was triggered following AP channel avoidance, which should not have occurred.

Note:

1. This version of firmware is applied to the Omada APP 4.25 or above