

Version Info:

1. Minimum FW Version for Update: 1.0.1 Build 20250704 Rel. 54810.
2. Recommended Omada Controller version 5.9 or above.
3. For downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Optimized the layout and navigation of the UI menu bar.

Bug fixed:

1. Fixed a bug where modifying the Web Server Port under standalone management did not take effect, preventing device login; rebooting restored normal operation.
2. Fixed a bug where, when adopting a device with Omada 6.0 and enabling manual DST in Site Settings, if the time zone was set to UTC+2, DST would start two hours earlier.
3. Fixed a bug where, after the Controller adopted two Main APs and one Client, the Client scanning for another Main AP showed the frequency band as 5 GHz.

Note:

1. This version of firmware is applied to Omada APP 4.19 or above