

Release Note for ER707-M2(UN)

v1.0/v1.20/v1.26/v1.30/v1.36/v1.60

Important Notice:

This firmware upgrade is irreversible. Please contact Omada technical support if a downgrade is required.

Version Info:

1. Applied Models:

- a) ER707-M2(UN) v1.0
- b) ER707-M2(UN) v1.20
- c) ER707-M2(UN) v1.26
- d) ER707-M2(UN) v1.30
- e) ER707-M2(UN) v1.36
- f) ER707-M2(UN) v1.60

2. Firmware Version:

1.4.2 Build 20260509 Rel. 32107

3. Minimum FW Version for Update:

- a) ER707-M2(UN) v1.0: 1.3.1 Build 20251009 Rel.67687 and above
- b) ER707-M2(UN) v1.20: 1.3.1 Build 20251009 Rel.67687 and above
- c) ER707-M2(UN) v1.26: 1.3.1 Build 20251009 Rel.67687 and above
- d) ER707-M2(UN) v1.30: 1.3.2 Build 20251009 Rel.61468 and above

e) ER707-M2(UN) v1.36: 1.3.2 Build 20251009 Rel.61468 and above

f) ER707-M2(UN) v1.60: 1.3.1 Build 20251009 Rel.67687 and above

To download any firmware version, please go to the [Omada Download Center](#).

4. Recommended Controller Version:

6.2.X

5. Recommended APP Version:

No.

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that the DNS service generates DNS64 addresses for domains that don't have AAAA records.
2. Fixed the issue of configuring the port forwarding rule for a Limited IP Address, which does not take effect after a device restart.

Additional Information:

No.