

**Release Note for ER7206(UN)
v2.0/v2.20/v2.26/v2.30/v2.36/v2.6 and ER7206(IN)
v2.28/v2.38/v2.8**

Version Info:

1. Applied Models:

- a) ER7206(UN) v2.0
- b) ER7206(UN) v2.20
- c) ER7206(UN) v2.26
- d) ER7206(UN) v2.30
- e) ER7206(UN) v2.36
- f) ER7206(UN) v2.6
- g) ER7206(IN) v2.28
- h) ER7206(IN) v2.38
- i) ER7206(IN) v2.8

2. Firmware Version:

2.3.2 Build 20260509 Rel. 21080

3. Minimum FW Version for Update:

- a) ER7206(UN) v2.0: 2.2.2 Build 20250724 Rel.11109 and above
- b) ER7206(UN) v2.20: 2.2.2 Build 20250724 Rel.11109 and above

- c) ER7206(UN) v2.26: 2.2.2 Build 20250724 Rel.11109 and above
- d) ER7206(UN) v2.30: 2.2.3 Build 20250929 Rel.69818 and above
- e) ER7206(UN) v2.36: 2.2.3 Build 20250929 Rel.69818 and above
- f) ER7206(UN) v2.6: 2.2.2 Build 20250724 Rel.11109 and above
- g) ER7206(IN) v2.28: 2.2.2 Build 20250724 Rel.11109 and above
- h) ER7206(IN) v2.38: 2.2.3 Build 20250929 Rel.69818 and above
- i) ER7206(IN) v2.8: 2.2.2 Build 20250724 Rel.11109 and above

To download any firmware version, please go to the [Omada Download Center](#).

4. Recommended Controller Version:

6.2.X

5. Recommended APP Version:

No.

New Features:

No.

Enhancements:

No.

Bug Fixed:

1. Fixed the issue that the DNS service generates DNS64 addresses for domains that don't have AAAA records.
2. Fixed the issue of configuring the port forwarding rule for a Limited IP Address, which does not take effect after a device restart.

Additional Information:

No.