

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

- 1. Firmware Version:** 1.0.8 Build 20260515 Rel. 13300
- 2. Applied Model:** EAP725-Outdoor 1.0
- 3. Minimum FW Version for Update:** 1.0.6 Build 20251222 Rel. 44323.
- 4. Recommended Omada Controller version:** 5.15.
- 5. Recommended Omada App version:** 4.25.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed:

1. Fixed an issue where specific mDNS packets could cause the device to freeze.
2. Fixed an issue where a potential deadlock might occur when a VLAN pool is configured and clients fail to obtain an IP address via DHCP.
3. Fixed an issue where device performance might be affected after enabling the Prohibit Wi-Fi Sharing feature.