

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.1.9 Build 20260517 Rel. 24459
2. **Applied Model:** EAP787 v1.0
3. **Minimum FW Version for Update:** 1.1.2 Build 20251013 Rel. 32717
4. **Recommended Omada Controller version:** 5.15
5. **Recommended Omada App version:** 4.24
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware to improve overall firmware security.

Bug Fixed:

1. Fixed an issue where the 6 GHz SSID would disappear and could only be restored by rebooting the AP.
2. Fixed an issue where, after MLO was enabled, an iPhone 16 Pro (iOS 26.3) could not obtain an IP address after several roaming attempts over time.
3. Fixed an issue where Wi-Fi interference detection scanned channels that are not supported.
4. Fixed a potential deadlock issue where clients could not obtain an IP address via DHCP when a VLAN pool was configured.
5. Fixed an issue where specific mDNS packets could cause the device to become unresponsive.
6. Fixed an issue where the device become stuck after running for a certain period of time.

Additional Information:

1. Optimized the RED Certification.