

## **Important notice**

This firmware version does not support downgrade. If you encounter any issues after upgrading, please contact Omada Technical Support.

## **Version info:**

### 1. Applied Models

- a) ER707-M2(UN) v1.0
- b) ER707-M2(UN) v1.20
- c) ER707-M2(UN) v1.26
- d) ER707-M2(UN) v1.30
- e) ER707-M2(UN) v1.36
- f) ER707-M2(UN) v1.60

### 2. Firmware Versio:1.4.4 Build 20260625 Rel. 43063

### 3. Minimum FW Version for Updat:

- a) ER707-M2(UN) v1.0: 1.3.1 Build 20251009 Rel.67687 and above
- b) ER707-M2(UN) v1.20: 1.3.1 Build 20251009 Rel.67687 and above
- c) ER707-M2(UN) v1.26: 1.3.1 Build 20251009 Rel.67687 and above
- d) ER707-M2(UN) v1.30: 1.3.2 Build 20251009 Rel.61468 and above
- e) ER707-M2(UN) v1.36: 1.3.2 Build 20251009 Rel.61468 and above
- f) ER707-M2(UN) v1.60: 1.3.1 Build 20251009 Rel.67687 and above

### 4. Recommended App Version: NO

### 5. Recommended Controller Version: 6.2.14

For downloading of any firmware version, please refer to Omada Download Center.

## **New features**

NO

## **Enhancements**

NO

## **Bug Fixes**

- 1.Improved overall system stability and reliability.
- 2.Updated the Geo-IP database to improve location accuracy for certain IP addresses.
- 3.Fixed an issue where SNMP access via OpenVPN could fail in specific scenarios.
- 4.Fixed an issue where stale routing entries might remain after WAN disconnection under certain conditions.
- 5.Fixed an issue that could prevent WireGuard Client traffic from being forwarded correctly.
- 6.Fixed an issue where Port Forwarding rules with specified source IP addresses might not take effect after a device reboot.
- 7.Fixed an issue in dual-stack environments where domains with IPv4-only records could not be accessed properly.
- 8.Fixed an issue in Standalone Mode where modifying a VPN user could unexpectedly affect other VPN user entries.