

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.0 Build 20260630 Rel.83311
2. **Applied Model:**
 - a) DR3650v(EU) v1.0
 - b) DR3650v(EU) v1.20
3. **Recommended Omada Controller version:** 6.2.14.
4. **Recommended Omada App version:** 5.3.
5. **Minimum FW Version for Update:**
 - a) EU v1.0: 1.1.0 Build 20250801 Rel.81737
 - b) EU v1.20: 1.1.1 Build 20250929 Rel.81227

New Features:

1. Add support for V6plus/DS-Lite Dial-up.
2. Add support for configuring multiple segment of DHCP IP pool when acting as DHCP server.
3. Add support for showing a list of clients obtaining IP addresses via DHCP when adopted on controller.
4. Add support for multi-channel configuration, currently support entering standalone UI to configure while disconnected from controller.
5. Add support for SpeedTest.
6. Add support for configuring ports of SIP ALG.
7. Add support for NAT Traversal.

Enhancements:

1. Optimized boot up time.
2. Optimized system stability.
3. Optimized menu layout.
4. Optimized efficiency of Network configuration deployment.
5. Optimized the resource consumption of traffic statistic.
6. Optimized the configuration of Load Balance.
7. Optimized configuration logic of VPN.
8. Expanded SD-WAN capacity.
9. Enhanced device security.

Bug Fixed:

1. Fixed several known issues.

