

Release Note

Important Notice:

This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.8.3 Build 20260617 Rel. 36045
2. **Applied Model:** EAP613 v2.0
3. **Minimum FW Version for Update:** 1.8.0 Build 20260312 Rel. 14111
4. **Recommended Omada Controller version:** 6.1.0.
5. **Recommended Omada App version:** 5.1.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Enhancements:

1. Encrypted the firmware and optimized the algorithm to enhance the overall security of the firmware.
2. Optimized the response time for loading and editing macfilter configurations.

Bug Fixed:

1. Fixed an issue where clients experienced communication anomalies after roaming in certain scenarios.
2. Fixed an issue where devices would occasionally reboot under specific operations.
3. Fixed an issue where the timeout rate for large ICMP packet transmission was abnormally high.

Additional Information:

1. Adapted to the RED certification requirement.