

Release Note

Important Notice:

This firmware version does not support downgrade. If a downgrade is required, please contact Omada Technical Support..

Version Info:

1. **Firmware Version:**1.4.5 Build 20260722 Rel. 15863

2. **Applied Model:**

- a) ER707-M2(UN) v1.0
- b) ER707-M2(UN) v1.20
- c) ER707-M2(UN) v1.26
- d) ER707-M2(UN) v1.30
- e) ER707-M2(UN) v1.36
- f) ER707-M2(UN) v1.60

3. **Recommended Omada Controller version:** 6.2.14

4. **Recommended Omada App version:**

N/A

5. **Minimum FW Version for Update:**

- a) ER707-M2(UN) v1.0: 1.3.1 Build 20251009 Rel.67687 and above
- b) ER707-M2(UN) v1.20: 1.3.1 Build 20251009 Rel.67687 and above
- c) ER707-M2(UN) v1.26: 1.3.1 Build 20251009 Rel.67687 and above
- d) ER707-M2(UN) v1.30: 1.3.2 Build 20251009 Rel.61468 and above
- e) ER707-M2(UN) v1.36: 1.3.2 Build 20251009 Rel.61468 and above
- f) ER707-M2(UN) v1.60: 1.3.1 Build 20251009 Rel.67687 and above

For downloading of any firmware version, please refer to Omada Download Center.

New Features:

- 1. None

Enhancements:

- 1. None

Bug Fixed:

- 1. Increased the security of the equipment
- 2. Updated the national geographic database to resolve the issue of inaccurate corresponding regions for certain IPs
- 3. Resolved the problem of failed access to SNMP through Openvpn in certain scenarios
- 4. Resolved the issue where routes were not correctly deleted after WAN disconnection in certain situations
- 5. Resolved the problem where Wireguard client could not act as an internet proxy
- 6. Resolved the issue where port forwarding rules with specified source IP did not take effect after device restart

7. Resolved the problem of being unable to access domain names with only IPv4 addresses in dual-stack scenarios
8. Fixed the issue where modifying a certain VPN user in standalone mode caused other users to be abnormally deleted