

Release Note

Important Notice:

This firmware version does not support downgrade. If a downgrade is required, please contact Omada Technical Support..

Version Info:

1. **Firmware Version:** 1.3.5 Build 20260722 Rel. 15891

2. **Applied Model:**

- a) ER7406(UN) v1.0
- b) ER7406(UN) v1.20
- c) ER7406(UN) v1.26
- d) ER7406(UN) v1.6

3. **Recommended Omada Controller version:** 6.2.14

4. **Recommended Omada App version:**

N/A

5. **Minimum FW Version for Update:**

- a) ER7406(UN) v1.0: 1.2.2 Build 20250724 Rel.11109 and above
- b) ER7406(UN) v1.20: 1.2.3 Build 20250929 Rel.69818 and above
- c) ER7406(UN) v1.26: 1.2.3 Build 20250929 Rel.69818 and above
- d) ER7406(UN) v1.6: 1.2.2 Build 20250724 Rel.11109 and above

For downloading of any firmware version, please refer to Omada Download Center.

New Features:

- 1. None

Enhancements:

- 1. None

Bug Fixed:

- 1. Improved overall system stability, reliability, and security.
- 2. Updated the Geo-IP database to improve location accuracy for certain IP addresses.
- 3. Fixed an issue where SNMP access via OpenVPN could fail in specific scenarios.
- 4. Fixed an issue where routing entries might not be removed correctly after WAN disconnection under certain conditions.
- 5. Fixed an issue where WireGuard Client traffic could not be forwarded correctly.
- 6. Fixed an issue where Port Forwarding rules with specified source IP addresses might not take effect after device reboot.
- 7. Fixed an issue in dual-stack environments where domains with IPv4-only records could not be accessed properly.
- 8. Fixed an issue in Standalone Mode where modifying a VPN user could unexpectedly affect other VPN user entries.

