

Release Note

Version Info:

1. **Firmware Version:** 1.2.3 Build 20260613 Rel. 32279.
2. **Applied Model:** EAP723 v2.0/v2.20/v2.26/v2.6.
3. **Minimum FW Version for Update:** 1.1.2 Build 20250901 Rel. 74897.
4. **Recommended Omada Controller version:** 6.1.
5. **Recommended Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

New Features:

1. Added support for dynamic VLAN assignment through DHCP Option 82.

Bug Fixed:

1. Fixed an issue where clients could not ping the device over IPv6 when Management VLAN was enabled.
2. Fixed an issue where the device could become unresponsive after multiple Force Provision or Move to Site operations.
3. Fixed an issue where the device could unexpectedly reboot when multicast filtering settings were modified.
4. Fixed an issue where the device could unexpectedly reboot in certain scenarios.
5. Fixed an issue where enabling Guest Network on an existing MLO SSID could trigger an unexpected interface restart.
6. Fixed an issue where the header of the root.ubi file could be overwritten with zeros.