

Release Note

Version Info:

1. **Firmware Version:** 1.4.3 Build 20260818 Rel. 14057.
2. **Applied Model:** EAP772 v2.0/v2.20
3. **Minimum FW Version for Update:** 1.3.2 Build 20250901 Rel. 52255.
4. **Recommended Omada Controller version:** 6.1.
5. **Recommended Omada App version:** 5.1.
6. For downloading any firmware version, please refer to [Omada Download Center](#).

Bug Fixed:

1. Fixed an issue where the AP could become unresponsive under certain conditions.
2. Fixed an issue where clients could lose their VLAN assignment after roaming when WPA-Enterprise and 802.11r were enabled on the SSID.
3. Fixed a memory leak issue that could occur when Fast Roaming was enabled.
4. Fixed an issue where abnormal behavior could occur with 802.1X VLAN in certain scenarios.
5. Fixed an issue where iPhone 16 Pro clients could fail to obtain an IP address after repeated roaming when MLO was enabled.
6. Fixed an issue where ACL configurations could be lost in certain scenarios.
7. Fixed an issue where iPhone 17 Pro Max clients could disconnect and reconnect repeatedly when connected to a tri-band MLO network.
8. Fixed an issue that could cause firmware upgrade failures in certain scenarios.
9. Fixed an issue where the device could crash in certain roaming scenarios.
10. Fixed a stability issue that could occur when clients reassociated after an SSID configured with a VLAN pool was disabled and then re-enabled.
11. Fixed several issues related to AFC functionality.