

Release Note

Version Info:

1. **Firmware Version:** 1.0.9 Build 20260818 Rel. 17285
2. **Applied Model:** EAP725-Outdoor v1.0
3. **Minimum FW Version for Update:** 1.0.6 Build 20251222 Rel. 44323
4. **Fully Adapted Omada Controller version:** 5.15.
5. **Fully Adapted Omada App version:** 4.25.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Enhancements:

1. Optimized overall system stability.

Bug Fixed:

1. Fixed an issue where, after changing the device fallback IP, the device web UI could intermittently become inaccessible.
2. Fixed an issue where device memory usage could continuously increase over time.
3. Fixed an issue where, in WPA-Enterprise + 802.11r SSID deployments, clients could lose VLAN configuration after roaming.
4. Fixed an issue where clients could not connect to an MLO SSID under certain conditions.