

Release Note

Version Info:

1. **Firmware Version:** 1.2.4 Build 20260816 Rel. 35251
2. **Applied Model:** EAP725-Wall v1.0/v1.20
3. **Minimum FW Version for Update:** 1.1.2 Build 20250901 Rel. 74897
4. **Fully Adapted Omada Controller version:** 6.1.
5. **Fully Adapted Omada App version:** 5.0.
6. For downloading any firmware version, please refer to [Omada Download Center](#). For more information about firmware version number and fully adapted controller version, please refer to [Announcement on the Change of Omada Product Firmware Version Numbers](#).

Enhancements:

1. Optimized overall system stability.

Bug Fixed:

1. Fixed an issue where, under specific configurations, mDNS Query packets were not forwarded correctly.
2. Fixed an issue where clients could repeatedly disconnect and reconnect under specific configurations.
3. Fixed an issue where the web UI could not be accessed after manually configuring the device fallback IP.
4. Fixed an issue where, under specific RADIUS + WPA-Enterprise SSID configurations, all wireless network interfaces could go down.
5. Fixed an issue where Dynamic VLAN did not work with 802.1X.
6. Fixed an issue where, in WPA-Enterprise SSID + 802.11r deployments, clients could lose VLAN configuration after roaming.