

**Bundled Firmware:**

EAP110\_V1, EAP110\_V2 EAP110\_V4

EAP115\_V1, EAP115\_V2 EAP115\_V4

EAP225\_V1, EAP225\_V2 EAP225\_V3

EAP225-Outdoor\_V1

EAP110-Outdoor\_V1 EAP110-Outdoor\_V3

EAP245\_V1 EAP245\_V3

EAP115-Wall\_V1 (EAP115-Wall is suitable for EU version only)

EAP225-Wall\_V2

EAP230-Wall\_V1

EAP235-Wall\_V1

EAP320\_V1 EAP320\_V2

EAP330\_V1 EAP330\_V2

**Bug Fixed:**

1. Upgrade Log4j to 2.17 to fix the vulnerability CVE-2021-44228 and CVE-2021-45046. Please refer to FAQ 3255 for more details.

**Notes:**

1. To use Omada Controller 3.2.X new features, you need to upgrade your EAP's firmware to the corresponding version.
2. Once upgraded to this version of Omada Controller, you will NOT able to downgrade to an earlier version.