

**Bundled Firmware:**

EAP110\_V1, EAP110\_V2 EAP110\_V4  
EAP115\_V1, EAP115\_V2 EAP115\_V4  
EAP225\_V1, EAP225\_V2 EAP225\_V3  
EAP225-Outdoor\_V1  
EAP110-Outdoor\_V1 EAP110-Outdoor\_V3  
EAP245\_V1 EAP245\_V3  
EAP115-Wall\_V1 (EAP115-Wall is suitable for EU version only)  
EAP225-Wall\_V2  
EAP230-Wall\_V1  
EAP235-Wall\_V1  
EAP320\_V1 EAP320\_V2  
EAP330\_V1 EAP330\_V2

**Bug Fixed:**

1. Upgrade Log4j to 2.17 to fix the vulnerability CVE-2021-44228 and CVE-2021-45046. Please refer to [FAQ 3255](#) for more details.

**Notes:**

1. To use new features on Omada Controller 3.2.X, you need to upgrade your EAP's firmware to the corresponding version.
2. The Omada Controller program needs to use the system's netstat command. If the Linux system does not have net-tools installed (which contain the netstat command), the program may not be able to run normally.
3. Support 64-bit Linux operating system including Ubuntu 14.04/16.04/17.04/18.04, CentOS 6.x/7.x and Fedora 20 or above, Debian 9.8.
4. Once upgraded to this version of Omada Controller, you will NOT able to downgrade to an earlier version.