Modifications and Bug Fixes:

New Features/Enhancement:
1.Improve stability of the EAP110
2.Optimize the inform mechanism between EAP and EAP controller.
3.Optimize the upgrade mechanism when you use the EAP controller to upgarde the firmware of EAP.

Bug Fixes:
1.Fixed the bug that you cannotd Group Member when the MAC Group name contains any blank spaces.
2.Fixed the bug that the MAC Group cannot work with the SSID which contains any blank spaces.
3.Fixed the bug that the RTS Threshold cannot choose back to 2347 if you changed it before.

Notes:

1. You can only upgrade to the US firmware after update.
2. Transmission power is compliant with FCC.
3. If you upgrade this firmware, please also upgrade your EAP Controller to EAP Controller V2.4.2 or higher version.