Modifications and Bug Fixes:

First firmware released.

Notes:

1. Transmission power is compliant with FCC.
2. Support EAP Controller V2.4.x or higher version.