This firmware fully adapts the Omada SDN platform and only compatible with Omada Controller v4.1.5 or above.
If you are using an old Omada controller and plan to upgrade this firmware for EAP, you must upgrade the Omada Controller as well: Upgrade Guide

New Feature/Enhancement:

1. Add automatic Tx Power deployment function.

2. Add the feature that when using Migration moving EAP to a invalid IP address of Omada Controller, the EAP will roll back.

3. Add support for displaying CPU utilization, memory utilization, and bandwidth-related configuration in the Standalone mode of the Omada APP.

4. Optimize the problem that sometimes EAP resets with an unstable power supply.

Bug fixed:

1. Fixed the bug that the client list and block list cannot display icons of Huawei, Samsung or some other Android phones in the Standalone mode of the Omada APP.

Notes

1. For EAP115 v4 only.

2. This version of firmware is applied to the Omada APP of version 3.2.3x or above.