RELEASE NOTE

For the following model:

Product Description: AC1200 Wireless Dual Band Gigabit VoIP VDSL/ADSL Modem Router

Model No: Archer VR1210v 1.0

Trademark: **TP-Link**

File Name: Archer VR1210v 1.0_2.0.0 0.9 v6041.0 Build 221027 Rel.12900n.bin
Release Time: 2022.11.21
MD5: afe4ccd33683b4d518d02746af3d0c65
Firmware Version: 2.0.0 0.9 v6041.0 Build 221027 Rel.12900n

Modifications:

1 Fix the problem that IPv6 dial-up failed, and the LAN side clients could not access the IPv6 Internet.
2 Fix the problem that a certain Alcate Dongle cannot access the Internet after obtaining the address.
3 Optimize the LAN to WAN (PPPoE) performance.
4 Fix the problem that DHCPv6 Client DUID value of PPPoE IPv6 dial-up is all 0, so when multiple devices are connected at the same time, they cannot obtain the address normally.