Release Note

Important Notice:
This firmware upgrade is irreversible. Contact support if issues are encountered after the firmware upgrade.

Version Info:

1. **Firmware Version:** 1.2.6 Build 20261027 Rel. 26212
2. **Applied Model:** AP9778 v1.0
3. **Minimum FW Version for Update**: 1.0.1 Build 20230706 Rel. 72488
4. **Fully Adapted Omada Controller version:** 5.9.
5. **Fully Adapted Omada App version:** 4.10.
6. For downloading any firmware version, please refer to Omada Download Center.

New Features:

1. Added support for importing and exporting encrypted configuration files in Standalone mode.

Enhancements:

1. Optimized overall system stability and security.
2. Optimized the supported security modes for MLO SSIDs in Standalone mode.

Bug Fixed:

1. Fixed several security vulnerabilities.
2. Fixed issues related to MLO client association, MAC authentication, MAC filtering, and Dynamic VLAN assignment.
3. Fixed issues where Dynamic VLAN assignments could be lost after client roaming.
4. Fixed several issues related to Portal authentication, HTTPS redirection, and authentication enforcement.
5. Fixed issues that could cause AP processes to crash or devices to restart unexpectedly.
6. Fixed issues related to SSID VLAN configuration, wireless interface initialization, and client connectivity.
7. Fixed issues affecting certain CLI commands and diagnostic functions.

Additional Information:

1. Adapted for RED Certification.