Recommended Controller Software Version: Omada Controller v3.1.x or above

Bug Fixed:

1. Fixed the bug that the channel limit feature doesn't work.

Notes:

1. For EAP225-outdoor v1 only.

2. Your device's configuration won't be lost after upgrading.