TP-Link FW Release Notes

Product Name	TD-WR850N(ESWISP) 2.0
Firmware Version	3.16.0 0.9.1 v6011.0 Build 200902 Rel.22112n
Release Date	Sep 2, 2020

Release purposes:

Change Agile config version from 2.0 to 1.1.

Display the Main function difference between version 200902 to version 19011.

Change items (Include New features, feature changes, bug fix)

No.	Description	Note
1	Support 2 level accounts function.	
2	Add RE mode.	
3	Support TR143 v1.1.0.	
4	Support use TR069 to have wifi neighbour scan.	
5	Support Agile ACS 1.2.	
6	Fix security issue："CVE-2018-15701"，which DoS attack may leads httpd fail.	
7	In Status web page, it will show WAN connection link rate.	
8	Show wireless client information, include wireless standard，channel width，rx/tx tranffic，signal,connection speed.	
9	Enable LAN/WAN node data Statistics function by default, you can use TR069 to get Statistics data.	
10	Add display of product ID in FW upgrade page.	
11	Add support for Option 43.	
12	Add support of IPv6 PD only function.	
13	Show LAN Linkup/down in System Log.	
14	Show link rate in Wireless Statistics.	
15	In Network Map page, show duplexmode info for Lan port.	
16	IGMP version switch：can choose v2 or v3.	
17	Auto Reboot Custom time，can choose 1-30 day.	
18	Modify trunk design of TxBurst and WMM，enable TxBurst by default，won't select WMM in web page.	
19	Show SN item in bottom part of WebUI.	
20	Add three flash support ：EN25QH32B/EN25QH64A/XM25QH64A.	

21	Enable CWMP by default.	