Recommended Controller Software Version: Omada Controller v5.0.30 or above

New Feature/Enhancement:

1. Add support for MAC-Based Authentication with encrypted SSID.

2. Add support for 802.11r fast roaming protocol.

3. Add support for VLAN information of PPSK clients in Controller mode.

4. Increased the PSK entry limit for PPSK without RADIUS from 50 to 128 in Controller mode.

5. Added button to enable/disable cloud-connection behavior in Standalone mode.

Bug Fixed:

1. Fixed the bug that EAP will sometimes drop packets from some IoT devices.

Notes:

1. For EAP225 v4 only.

2. This version of firmware is applied to the Omada APP of version 3.0.X or above.

3. After install this firmware, the EAP will not be able to install lower versions of firmware.

4. This firmware is only compatible with Omada controller v4.1.5 or above. If you are using the old Omada controller and need to manage EAP225, you must upgrade the Omada controller to version 4.1.5 or above. You can follow Omada Controller Upgrade Guide to upgrade omada controller.