This firmware support Controller 5.7 management features, but only can be adopted in Omada SDN Controller v5.9 or above.

New Feature/Enhancement:

1. Add support modifying SFP port Duplex as Full /Auto mode.

BUG Fixed:

1. Fix the bug of memory usage curve anomaly.

2. Fix the bug of the CPU usage curve being abnormal after multiple LAN network been created.

3. Fix the bug of probable packet loss when the device runs for a long time.

4. Fix the bug of Port Forwarding data forwarding exception under multi-WAN.

5. Fix the bug of probable abnormal reboot of the device.

Notes:

1. Your device's configuration won't be lost after upgrading.