Enhancements

1. Optimized the stability of the stacking system.

Bug fixed

1. Fixed a probabilistic packet loss issue when using the device to ping other devices.

2. Fixed a bug where the MGMT interface occasionally failed to obtain an IP address or link up properly.

3. Fixed multiple bugs related to PIM.

4. Fixed a bug that could occasionally cause device anomalies when using the Locate function on the Controller.