Recommended Controller Software Version: Omada Controller v5.14 or above

Minimum FW Version for Update: 1.0.2 Build 20210823 Rel. 35851 and above, for downloading of any firmware version, please refer to Omada Download Center.

New Features/Enhancements:

1. Improved Mechanism: Editing entries in PPSK profile will no longer affect wireless connection of clients using other unedited entries.

2. Improved wireless connection stability with WPA-Enterprise encryption.

Notes:

1. This version of firmware is applied to the Omada APP v4.17 or above.